

Screen >>

A control panel featuring a central rectangular screen. To the left of the screen is a red square button with a white downward arrow and a yellow triangle warning symbol. Below that is a white square button with a black padlock icon. To the right of the screen are four square buttons: an upward arrow, a downward arrow, a leftward arrow with an 'X', and a checkmark in a circle. Below the screen are two red square buttons: one with a white exclamation mark in a triangle and another with a white forklift icon. The panel is secured with two screws at the top corners, each labeled 'WORK P.C.'.

4000274010 C


A set of directional controls including a central joystick and four circular buttons with arrows pointing up, down, left, and right. The joystick is surrounded by four circular buttons with arrows pointing up, down, left, and right. To the right of the joystick is a larger button with a white icon of a forklift's mast and carriage.

An ignition switch with a key inserted. The key has a logo on it. To the right of the switch is a white icon of a person operating a forklift. Below the icon are three small circles of varying sizes.

A large, grey, circular gear mechanism with a metal hook and a thin rod attached to it. The gear has several teeth and a central hub.

Haulotte >>

450 E 50





NOTICE




1 + 2

=



2





1




1 + 2

=



2




1




1 + 2

=



2




PROCEDURE




4000274030 a sa

1




2





NOTICE



4000361570 n 98





CS

Haulotte

4000137720 e sa